

APPENDIX 2

Workorders

NEWPCC

**Workorder:
12529**

CLOSED

**Corrective Maintenance - Plumbing
MP 5(SEAL WATER LINE)**

Equipment: MP5MISC -MISC MAIN BUILDING PUMPS

Requested by: bromance

Created on: Jun 24 2002 11:23

Completed by: smeg

Completed on: Jul 19 2002 14:16

Closed on: Jul 22 2002 15:11

Workorder Comments

PLEASE REPAIR BROKEN SEAL WATER LINE ON MP 5.

MP 5 Work Orders

Added

5072

4612

2151

2150

1478

1444

Oct 31, 2002

BDM

NEWPCC

**Workorder:
12508**

CLOSED

Corrective Maintenance - Plumbing

MP 5(SEAL WATER LINES)

Equipment: MP5MECHMISC -MISC MP5 MECH

Requested by: bromance

Created on: Jun 18 2002 13:02

Completed by: ggreenaw

Completed on: Jul 12 2002 12:31

Closed on: Jul 15 2002 8:07

Workorder Comments

PLEASE REPLACE SEAL WATER LINES FOR MP 5.

NEWPCC

**Workorder:
12455**

WINIT

CM-Corrective Maintenance - Mechanical

MP 5 (SUCTION VALVE NOT CLOSE

Equipment: M150FV - SUCTION VALVE MP#5

Requested by: bromance

Created on: Jun 6 2002 11:16

Completed by:

Completed on:

Closed on:

Workorder Comments

SUCTION VALVE WILL NOT CLOSE ON MP 5.

NEWPCC

**Workorder:
12456**

CLOSED

Corrective Maintenance - Electrical
MP 5(SEAL H2O SOLENIOD)

Equipment: MP5MECHMISC -MISC MP5 MECH

Requested by: bromance

Created on: Jun 6 2002 11:18

Completed by: jamos

Completed on: Jun 18 2002 11:00

Closed on: Jun 21 2002 8:14

Workorder Comments

PLEASE REPLACE SEAL WATER SOLENIOD ON MP 5.

Note there is a new solenoid on the line already....suspect bad line.
Advised the plumber. J.Amos.....

NEWPCC

**Workorder:
12292**

CLOSED

Corrective Maintenance - Electrical
MP5 SHOWS NO FLOW

Equipment: MAM150FT -FLOW TRANSMITTER MP.5 PUMP

Requested by: kfumerton

Created on: Apr 3 2002 14:21

Completed by: jamos

Completed on: Apr 10 2002 11:32

Closed on: Apr 10 2002 14:34

Workorder Comments

NEWPCC

**Workorder:
12285**

CLOSED

Corrective Maintenance - Electrical
MP 5(NO FLOW INDICATION)

Equipment: MAM150FI -Flow Indicator For MP5

Requested by: bromance

Created on: Apr 3 2002 8:26

Completed by: jamos

Completed on: Apr 10 2002 11:34

Closed on: Apr 10 2002 14:33

Workorder Comments

MP 5 SHOWS NO FLOW WHEN RUNNING.

NEWPCC

**Workorder:
12057**

CLOSED

Corrective Maintenance - Plumbing

REPLACE 1 1/2 FLUSHING LINE

Equipment: MP5MECHMISC -MISC MP5 MECH

Requested by: kfumerton

Created on: Jan 16 2002 14:31

Completed by: bmacdona

Completed on: Feb 4 2002 13:22

Closed on: Feb 4 2002 13:37

Workorder Comments

repair leak on 10" inch flushing water line (work order went missing)
order pipe and fittings to complete rest of job as requested - civil
maintance also came to drill in well.

NEWPCC

**Workorder:
11188**

CLOSED

**Corrective Maintenance - Electrical
MP5 (LIMIT SW.)**

Equipment: MAM151VD -SUCTION VLV1 OPN. MP.5 PUMP

Requested by: bromance

Created on: May 14 2001 9:55

Completed by: jamos

Completed on: Jul 9 2001 14:51

Closed on: Jul 12 2001 10:52

Workorder Comments

PLEASE CHECK LIMIT SWITCH ON MP 5 DOES NOT SHOW IT IS CLOSED. (SUCTION VALVE)

NEWPCC

**Workorder:
11186**

CLOSED

**Corrective Maintenance - Mechanical
MP 5 (GLANDS)**

Equipment: MP5MECHMISC -MISC MP5 MECH

Requested by: bromance

Created on: May 10 2001 9:13

Completed by: hloewen

Completed on: May 14 2001 10:23

Closed on: May 25 2001 8:56

Workorder Comments

PLEASE ADJUST GLANDS ON MP 5.

NEWPCC

**Workorder:
11187**

CLOSED

**Corrective Maintenance - Electrical
MP 5(SEAL WATER ALARM)**

Equipment: MP5ELECMISC -MISC MP5 ELEC

Requested by: bromance

Created on: May 10 2001 9:17

Completed by: jamos

Completed on: Jul 9 2001 14:50

Closed on: Jul 12 2001 10:52

Workorder Comments

PLEASE CHECK SEAL WATER ALARM ON MP 5, THIS ALARM WILL NOT CLEAR.

Needs plumbing work as line is plugged.....

NEWPCC

**Workorder:
10579**

CLOSED

Corrective Maintenance - Electrical
MP 5 SEAL WATER SOLENIOD

Equipment: MP5ELECMISC -MISC MP5 ELEC

Requested by: bromance

Created on: Oct 24 2000 15:38

Completed by: rburr

Completed on: Oct 27 2000 10:33

Closed on: Oct 27 2000 10:33

Workorder Comments

PLEASE CHECK MP 5 SEAL WATER SOLENIOD.

NEWPCC	Workorder: 5072	CLOSED
Corrective Maintenance - Mechanical		
M MP#5 (PACKING)		
Equipment: MP5MECH -Main building pump 5 mechanical		
Requested by: C.WORTMAN	Created on: Aug 28 1997 00:00	
Completed by: WAYNER	Completed on: Aug 28 1997 00:00	
	Closed on: Sep 2 1997 00:00	
<hr/>		
Workorder Comments		
<hr/>		
PLEASE CHECK PACKING.		
ADD ONE RING OF 7/8" PACKING!!		

NEWPCC	Workorder: 4612	CLOSED
Corrective Maintenance - Mechanical		
M-MP#5 GLAND LEAK		
Equipment: MP5MECH -Main building pump 5 mechanical		
Requested by: MIKE H	Created on: Mar 21 1997 00:00	
Completed by: WAYNER	Completed on: Mar 24 1997 00:00	
	Closed on: Mar 26 1997 00:00	
<hr/> Workorder Comments <hr/>		
PUMP IS LEAKING SEAL WATER AT GLAND.		
ADJ. PACKING FOLLOWER!!		

0ct 8/1999 *Adjust Valve*
6959 *stem packing*
 Pne Greenaway

NEWPCC	Workorder: 2151	CLOSED
Corrective Maintenance - Mechanical		
M MP 5 FLOW SWITCH		
Equipment: MP5MECH -Main building pump 5 mechanical		
Requested by: GGAUTHIER	Created on: Apr 28 1995 00:00	
Completed by: WALTER	Completed on: May 4 1995 00:00	
	Closed on: May 10 1995 00:00	
<hr/>		
Workorder Comments		
<hr/>		
PLEASE INSTALL NEW FLOW SWITCH COMPLETE!		

NEWPCC	Workorder: 2150	CLOSED
Corrective Maintenance - Electrical		
E MP 5 FLOW SWITCH		
Equipment: MP5ELEC -Main building pump 5 electrical		
Requested by: GGAUTHIER	Created on: Apr 28 1995 00:00	
Completed by: SP/NM	Completed on: May 3 1995 00:00	
	Closed on: May 10 1995 00:00	
<hr/>		
Workorder Comments		
<hr/>		
PLEASE WIRE FLOW SWITCH		
REPLACED AND TESTED OK.		

NEWPCC	Workorder: 1478	CLOSED
Corrective Maintenance - Mechanical		
M MP5 GLAND		
Equipment: MP5MECH -Main building pump 5 mechanical		
Requested by: B HAMILTON	Created on: Nov 2 1994 00:00	
Completed by:	Completed on: Nov 1 1994 00:00	
	Closed on: Nov 3 1994 00:00	
<hr/>		
Workorder Comments		
<hr/>		
ADJUST GLAND. COMPLETE!!!!!!		

NEWPCC	Workorder: 1444	CLOSED
Corrective Maintenance - Mechanical		
M MP5 DISCHARGE LINE		
Equipment: MP5MECH -Main building pump 5 mechanical		
Requested by: B HAMILTON	Created on: Oct 24 1994 00:00	
Completed by: P.K.&HEINZ	Completed on: Oct 24 1994 00:00	
	Closed on: Oct 28 1994 00:00	
<hr/>		
Workorder Comments		
<hr/>		
SOUNDS LIKE A PIECE OF METAL IS IN DISCHARGE LINE. CHECKED OUT O.K.!		

NEWPCC

Workorder: 189

CLOSED

Corrective Maintenance - Mechanical

M MP 5 PUMP

Equipment: MAM150MM -MAIN PUMP #5 see comments for electric motor data

Requested by: GGAUTHIER

Created on: Nov 17 1993 00:00

Completed by: W PHILPOTT

Completed on: Nov 17 1993 00:00

Closed on: Nov 25 1993 00:00

Workorder Comments

PLEASE CHECK PACKING ON PUMP
GLAND REPACKED
REPACK PUMP

NEWPCC

Workorder: 120

CLOSED

Corrective Maintenance - Electrical
E- MP5 BEARING TEMP.

Equipment: MAM150TA -TEMP. ALARM MP.5 PUMP

Requested by: B ROMANCE

Created on: Oct 20 1993 00:00

Completed by: MJ RB

Completed on: Oct 20 1993 00:00

Closed on: Oct 28 1993 00:00

Workorder Comments

HIGH BEARING TEMP. ON MP5. PLEASE REPAIR
REPAIRED BAD CONNECTION AT PUMP